

# Water Main Facts


- Water main hit morning of Friday, May 15, near Chapel View Drive
  - One home directly affected
- Utility and emergency services contacted immediately
- South Jordan City, UDOT and A&W worked together to repair water main and affected home as quickly as possible
- Homeowner contacted immediately and steps taken to mitigate the problem
- 4:00 p.m. Water main repaired
- 5:00 p.m. Utilities restored and full use of upper level in home available
- 6:00-6:30 p.m. Water restored to affected residents

#### **Water Main Facts**

#### **Future Communication**

- Email database notification
- Information posted on project website











































LIPOI







LIPOIT





LIPOI

### **Current Activities**



I POI

#### **Public Involvement Overview**

- Access
- Quality
- Public Information
- Safety
- Mobilization



## Landscaping


#### Tree and Shrub Selection Criteria

- Adapted to harsh planting conditions
- Trees approved by cities
- Commercial availability
- · Consideration of maintenance requirements
- · Height and canopy restrictions for planting in narrow area
- · Salt tolerant plants
- · Heat and wind tolerant plants
- · Approved for planting under power lines
- Project budget constraints




#### Landscaping

#### Percentage of Total



### Landscaping

#### Percentage of Total





#### Landscaping

#### Tree Removals vs. New Trees

- 102 trees to be removed in the ROW
- 706 new trees will be planted



### **Median and Parkstrip Concept**





#### 700 W. Landscape Concept



11400 SOUTH ROADWAY LANDSCAPING 700 West Gore Areas



